



Worldwide repairs carried out with PolymerMetal®

REP-# 004



5 cracks in the casing of the water pump D-6300/80 at a land reclamation station was repaired with MM-metal SS-steelceramic and Hardener yellow.

MultiMetall
the MetalExistenceCompany®